

P.O Box 3072, Fitzroy, New Plymouth  
9 Swans Road, Bell Block, New Plymouth  
Phone: 06 7559139, Fax 06 7551410  
www.independentoilfield.co.nz



|                |             |
|----------------|-------------|
| ATTENTION      | Gary Turner |
| COMPANY        | SDI         |
| PURCHASE ORDER | 1153        |
| REPORT NUMBER  | 8741        |

|                    |                 |                          |           |                          |                    |                          |                    |                          |
|--------------------|-----------------|--------------------------|-----------|--------------------------|--------------------|--------------------------|--------------------|--------------------------|
| TOOL DESCRIPTION   | NM Drill Collar |                          |           |                          |                    | SIZE                     | 9-5/8"             |                          |
| NEW#USED           | MRP, RK-34      |                          |           | TALLY                    | 366-1/16"          | SERIAL NUMBER            | 84-283             |                          |
| TYPE OF INSPECTION | MT              | <input type="checkbox"/> | PT        | <input type="checkbox"/> | Visual/dimensional | <input type="checkbox"/> | Customer procedure | <input type="checkbox"/> |
|                    | DS-1 Cat 3-5    | <input type="checkbox"/> | APIRPTG-2 | <input type="checkbox"/> | Other              |                          |                    |                          |

Buffed outside diameter, threads and seals.

Carried out above inspection.

|                               |             |            |
|-------------------------------|-------------|------------|
| RESULTS:                      | Serviceable |            |
| Connection                    | PIN         | 7-5/8" REG |
| Outside Diameter              |             | 9-5/8"     |
| Internal Diameter             |             | 4-1/4"     |
| Tong Space                    |             |            |
| Pin Length                    |             | 5-3/16"    |
| Bevel Diameter                |             | 8-29/32"   |
| Stress Relief Groove Diameter |             | NA         |
| Stress Relief Groove Width    |             | NA         |
| Counter Bore Diameter         |             |            |
| Counter Bore Depth            |             |            |
| Bore Back Cylinder Length     |             |            |
| Bore Back Diameter            |             |            |

|                               |             |            |
|-------------------------------|-------------|------------|
| RESULTS:                      | Serviceable |            |
| Connection                    | BOX         | 7-5/8" REG |
| Outside Diameter              |             | 9-9/16"    |
| Internal Diameter             |             |            |
| Tong Space                    |             |            |
| Pin Length                    |             |            |
| Bevel Diameter                |             | 8-29/32"   |
| Stress Relief Groove Diameter |             |            |
| Stress Relief Groove Width    |             |            |
| Counter Bore Diameter         |             | 7-1/16"    |
| Counter Bore Depth            |             | 11/16"     |
| Bore Back Cylinder Length     |             | NA         |
| Bore Back Diameter            |             | NA         |

No relevant indications were observed at the time of inspection.

|           |   |
|-----------|---|
| COMMENTS: | Inspection post Face + Chase of Pin and Box |
|           |   |

NOTE: IF API TOLERANCES DO NOT PERMIT, MORE EXTENSIVE REPAIRS MAY BE REQUIRED

|           |                   |                |                               |
|-----------|-------------------|----------------|-------------------------------|
| INSPECTOR | Rick Christiansen | DATE INSPECTED | 15 <sup>th</sup> October 2014 |
|-----------|-------------------|----------------|-------------------------------|