

P.O Box 3072, Fitzroy, New Plymouth
9 Swans Road, Bell Block, New Plymouth
Phone: 06 7559139, Fax 06 7551410
www.independentoilfield.co.nz



ATTENTION	Gary Turner
COMPANY	Vause Well Services
PURCHASE ORDER	7758

TOOL DESCRIPTION		NM Drill Collar						SIZE		8.0"			
NEW/USED		VWS				TALLY		321.0"		SERIAL NUMBER		NZ-003	
TYPE OF INSPECTION		MPI	<input type="checkbox"/>	LPI	<input type="checkbox"/>	Visual/dimensional		<input type="checkbox"/>	Customer procedure		<input type="checkbox"/>		
		DS-1 Cat 3-5		<input type="checkbox"/>	APIRPTG-2		<input type="checkbox"/>	Other					

Buffed outside diameter, threads and seals.

Bored outside diameter, threads and seals.

RESULTS:	Serviceable	
Connection	PIN	6-5/8" Reg
Outside Diameter		8-1/8"
Internal Diameter		2-3/4"
Tong Space		27.0"
Pin Length		5.0"
Bevel Diameter		7-1/2"
Stress Relief Groove Diameter		5.410"
Stress Relief Groove Width		13/16"
Counter Bore Diameter		
Counter Bore Depth		
Bore Back Cylinder Length		
Bore Back Diameter		

Carried out above inspection.

ailed out above inspection.

RESULTS:	Serviceable	
Connection	BOX	6-5/8" Reg
Outside Diameter		8-1/8"
Internal Diameter		
Tong Space		48.0"
Pin Length		
Bevel Diameter		7-23/32"
Stress Relief Groove Diameter		
Stress Relief Groove Width		
Counter Bore Diameter		6-3/32"
Counter Bore Depth		5/8"
Bore Back Cylinder Length		8.0"
Bore Back Diameter		5-9/32"

AC yoke S/N	N/A	AC yoke test block S/N	N/A				
Black light meter S/N	N/A	Coil S/N	N/A				
Black light S/N	N/A	Black Light meter reading	N/A	H/ Banding required	PIN	<input type="checkbox"/>	BOX <input type="checkbox"/>

No relevant indications were observed at the time of inspection.

COMMENTS:	
-----------	--

NOTE: IF API TOLERANCES DO NOT PERMIT, MORE EXTENSIVE REPAIRS MAY BE REQUIRED

INSPECTOR	Shaun Gargan	DATE INSPECTED	13 th January, 2016
-----------	--------------	----------------	--------------------------------