

Client Order Ref. N° : TSA PO# 3380
 Report Ref N° : SG-2022-JKA-M00253
 Rev : 0



BUREAU VERITAS
TANK CONTAINER
 CLEANLINESS CERTIFICATE

ACCEPTED
 REJECTED

| | | | |
|------------------|---|-----------------|-----------------------------------|
| TANK NO | : NTTU 240011 - 9 | TANK TYPE | : UN Portable Tank |
| MANUFACTURE DATE | : 01-2012 | TARE WEIGHT | : 3650 kg |
| CAPACITY | : 23945 litres | GROSS WEIGHT | : 36000 kg |
| CLEANING DEPOT | : Tank Services Australia | INSPECTION DATE | : 12-08-2022 |
| PLACE OF ISSUE | : MELBOURNE | LOCATION | : MELBOURNE AUSTRALIA |
| CLEANING PROCESS | : Hot water, detergent, cold water, rinse and dry | CLIENT | : Tank Services Australia Pty Ltd |
| LAST CARGO | : MT CLEAN ISO | | |
| UN NO | : | | |
| NEXT CARGO | : NOT ADVISED | | |
| UN NO | : | | |

EXTERIOR free from all cargo and contamination

| | | |
|---------------------------------------|---|-----------------------------|
| Exterior frame, tank and walkways | YES <input checked="" type="checkbox"/> | |
| Manlid and valve compartments | YES <input checked="" type="checkbox"/> | If NO provide details below |
| Serial numbers and statutory markings | YES <input checked="" type="checkbox"/> | |
| Cargo labels removed | YES <input checked="" type="checkbox"/> | |

INTERIOR

| | | |
|---|---|-----------------------------|
| Entry made into tank by surveyor | YES <input checked="" type="checkbox"/> | |
| Free from odor | YES <input checked="" type="checkbox"/> | |
| Free from all cargo and contamination | YES <input checked="" type="checkbox"/> | If NO provide details below |
| Free from corrosion or pitting (if NO, report detail below) | YES <input checked="" type="checkbox"/> | |
| Dry | YES <input checked="" type="checkbox"/> | |

VALVES/FITTINGS free from all cargo and contamination

| | | |
|-------------|---|------------------|
| Valves | YES <input checked="" type="checkbox"/> | |
| Manlid Seal | YES <input checked="" type="checkbox"/> | FV SUPER TANKTYT |
| Dip-Pipe | YES <input type="checkbox"/> | Not fitted |

If NO provide details below

| | | |
|---------------|---|-----------------------|
| GAS FREE TANK | YES <input checked="" type="checkbox"/> | O2 : 20.8 % LEL : 0 % |
|---------------|---|-----------------------|

A thorough visual examination has been carried out to the interior of the tank, valves and fittings. The tank is clean and dry at time of inspection.

REMARKS :

Airline seal: 0245278
 Manlid seal: 0245279
 Bottom outlet seal: 0245280
 MINOR SCRATCHES, WATER MARKS AND BUFF MARKS TO INTERIOR.

NAME : KAPUR Jagadish

SIGNED :



DATE OF ISSUE : 13-08-2022



THIS REPORT IS BASED SOLELY UPON A VISUAL EXAMINATION OF THE TANK, AND THE EXAMINATION OF DOCUMENTS PROVIDED BY OTHERS. THE SURVEYOR ACCEPTS NO LIABILITY FOR ANY CONDITIONS THAT ARE NOT APPARENT DURING A NORMAL VISUAL INSPECTION, OR THAT MAY BE THE RESULT OF INACCURATE INFORMATION PROVIDED IN DOCUMENTS UPON WHICH THE SURVEYOR MUST RELY.

* SUBJECT ONLY TO THE CLEANLINESS OF THE TANK, INTERIOR, VALVES AND FITTINGS.