

P.O Box 3072, Fitzroy, New Plymouth
9 Swans Road, Bell Block, New Plymouth
Phone: 06 7559139, Fax 06 7551410
www.independentoilfield.co.nz



ATTENTION	Gary Turner
COMPANY	Vause Well Services
PURCHASE ORDER	7758

TOOL DESCRIPTION		NM Pony Collar						SIZE		8.0"			
NEW/USED		VWS				TALLY		128-3/4"		SERIAL NUMBER		NZ-010	
TYPE OF INSPECTION		MPI	☐	LPI	☐	Visual/dimensional		☐	Customer procedure		☐		
		DS-1 Cat 3-5		☐	APIRPTG-2		☐	Other					

Buffed outside diameter, threads and seals.

Carried out above inspection.

RESULTS:	Serviceable	
Connection	PIN	6-5/8" Reg
Outside Diameter	7-25/32"	
Internal Diameter	3-1/4"	
Tong Space	30.0"	
Pin Length	4-31/32"	
Bevel Diameter	7-7/16"	
Stress Relief Groove Diameter	5.407"	
Stress Relief Groove Width	3/4"	
Counter Bore Diameter		
Counter Bore Depth		
Bore Back Cylinder Length		
Bore Back Diameter		

RESULTS:	Serviceable	
Connection	BOX	6-5/8" Reg
Outside Diameter	7-7/8"	
Internal Diameter		
Tong Space	30.0"	
Pin Length		
Bevel Diameter	17-17/32"	
Stress Relief Groove Diameter		
Stress Relief Groove Width		
Counter Bore Diameter	6-3/32"	
Counter Bore Depth	21/32"	
Bore Back Cylinder Length	8-3/4"	
Bore Back Diameter	5-9/32"	

AC yoke S/N	N/A	AC yoke test block S/N	N/A				
Black light meter S/N	N/A	Coil S/N	N/A				
Black light S/N	N/A	Black Light meter reading	N/A	H/ Banding required	PIN	☐	BOX ☐

No relevant indications were observed at the time of inspection.

COMMENTS:	
-----------	--

NOTE: IF API TOLERANCES DO NOT PERMIT, MORE EXTENSIVE REPAIRS MAY BE REQUIRED

INSPECTOR	Shaun Gargan	DATE INSPECTED	13 th January, 2016
-----------	--------------	----------------	--------------------------------